

Project No: AFC002001030202
Project: Supplemental RI

Client: AFCEE

Location: Site 24 - Vandenberg AFB

Northing(ft): 2099346.2

Borehole ID: HGL70(24MW19B)

Date: 10/13/2003
Geologist: M. Jackson
Checked By: D. Smith, R.G.

Ground Surface Elevation(ft msl): 460.4

Easting(ft): 5801076.8

| | | SUBSURFACE PROFILE | | | 1 | CAMPLE | | т | T |
|---------------------|--------|---|-------------|-----------|------------|--------------|-----------|-------------|--|
| CODOCKI ACE PROFILE | | | 7 | | SAMPLE | | 4 | | |
| Depth | Symbol | Description | nscs | Elevation | Recovery % | Blow | PID (ppm) | Water Level | Remarks |
| 2- | | Gravel, sand, and silt | FL | 457 | , | | | | |
| 4 - | | Poorly graded sand Moderate yellowish brown, dry, loose, medium | SP | | | | | | |
| 6 | | grained | | 1 | 90 | 9/8/8 | 3.5 | 1 | |
| 8 | | at 5' color change to dark yellowish brown, slightly moist, slightly dense | | _ _452 | | | | | |
| 10- | | Sandy clay | CL | - | <u> </u> | | ļ | | |
| 12- | | Dark yellowish gray, moist, slightly soft Poorly graded sand | SP | | 100 | 50 for 2" | 2.4 | | |
| 14-1 | | Dark yellowish brown, slightly moist, medium grained, clayey sand lenses at 13' color change to pale yellowish brown, | | | | | | | |
| 16 | | slightly dense, some interbeds of clayey sand | | | 100 | 40/70 | 3.6 | | Sot tomporon, well with |
| 18- | | at 15' color change to light olive gray, very moist | | | | | | | Set temporary well with (screen from 15' - 25'). |
| 20 - | | at 20' pale olive, moist to saturated, dense, medium grained | | | 100 | 37/50 for 5" | 4.8 | Â | Collect groundwater sample |
| 22- | | medam granted | | 437 | | | | | (HGL-70-GW25) |
| 24 | | Clayey sand Mottled dark yellowish brown to pale olive, moist, | sc | | | | | | |
| 26- | | slightly dense, medium grained, 80% sand/20% clay | | 433 | 100 | 40/70 for 2" | 5.5 | | |
| 28 | | Sandy clay | CL | | | - | | | |
| 30 | | Yellowish gray, moist, stiff, medium grained sand | | 430 | | | <u> </u> | | |
| 32 | | Silty Clay Mottled moderate yellowish brown to light | | | 100 | 40/70 | 2.2 | ļ | |
| 1 / | | brown, very stiff | ٠,٠ | | | | | | |
| 34-1 | | | | 424 | | | | | |
| 36- | | Poorly graded sand | SP | 424 | 90 | 14/20/31 | 3.5 | | |
| 38- | | Grayish yellow green, slightly moist, slightly moist, slightly dense, medium grained | ł | 421 | | _ | | | |
| 40- | | | SW | 741 | 100 | 39/44/15 | 1.2 | | |

Drilled By: Layne Christensen

HydroGeoLogic, Inc.

Drill Method: Dual Tube Percussion

4600 Northgate Blvd., Suite 207 Sacramento, CA 95834

Drilling Equipment: AP-1000

(916) 614-8770 FAX (916) 614-8775

Sampling Equipment: 2" x 18" CA Mod Split Spoon

Boring Diameter: 10"

Total Depth Drilled: 75'

Sheet: 1 of 2



Project No: AFC002001030202

Project: Supplemental RI

Client: AFCEE

Location: Site 24 - Vandenberg AFB

Northing(ft): 2099346.2

Borehole ID: HGL70(24MW19B)

Date: 10/13/2003
Geologist: M. Jackson
Checked By: D. Smith, R.G.

Ground Surface Elevation(ft msl): 460.4

Easting(ft): 5801076.8

| SUBSURFACE PROFILE | | | | | SAMPLE | | | | |
|----------------------|---|---|------------|--------------|------------|--------------|--|-------------|--|
| Depth | Symbol | Description | USCS | Elevation | Recovery % | Blow Counts | PID (ppm) | Water Level | Remarks |
| 42- | | Well graded sand with gravel Pale green, slightly moist, medium grained, gravel to cobble size | sw | 416 | 100 | | | | |
| 46 | | Clayey silt Grayish blue green, moist, moderately stiff | ML | 412 | 100 | 14/25/40 | 4.8 | | Intermediate groundwater bearing zone not encountered. |
| 50 | 9 5 5 6 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 | Gravelly silty sand Grayish blue, slightly moist, 60% sand/25% gravel/15% silt, cobbles to 1.5% at 53' unit becomes moist | SW | | 100 | 49/70 for 4" | 3.3 | | S. ISSUMOISU |
| 54 - 56 - 58 - | | at 55' unit becomes grayish green, moist, slightly dense, gravel to 1" at 58' cobbles to 2.5" | | 402 | 100 | 50/60 for 5" | 3.5 | | |
| 60 | | Gravelly silt Grayish blue green, slightly moist, very stiff, cobbles to 1" | ML | 399 | 100 | 50/60 for 5" | 3.6 | | |
| 64 | 2 2 | Gravelly sand Grayish green, moist, coarse grained, pebbly, cobbly | sw | | | P-0-1 | | | Set temporary well (screen 65 to 75 feet) |
| 66- 68- | | at 64' unit becomes very moist at 68' unit becomes very moist to saturated | | | 0 | 70 for 5" | N/A | ¥ | Collect groundwater sample (HGL-70-GW75). |
| 70 72 | o °g | at 70' increase in clay content to clayey gravelly sand, saturated, very dense, gravel to 0.5" | avelly 100 | 31/70 for 4" | 4.1 | | Boring converted to deep well 24-MW-19B. | | |
| 74- | | Mudstone Olive gray to light olive gray, slightly moist, hard, | rock | 387 | | | | | |
| 76- 78- 80- | | bedrock, fissile | | 557 | 100 | 30/70 for 5" | 3.1 | | |

Drilled By: Layne Christensen

HydroGeoLogic, Inc. 4600 Northgate Blvd., Suite 207

Sacramento, CA 95834

Drilling Equipment: AP-1000

Drill Method: Dual Tube Percussion

(916) 614-8770 FAX: (916) 614-8775

Sampling Equipment: 2" x 18" CA Mod Split Spoon

Boring Diameter: 10"

Total Depth Drilled: 75'

Sheet: 2 of 2